


Benelli



MatchGun MG2

For a spring wound clockwise, put the cut left end at 9:00, with the first complete turn aligned with the red line. Adjust the angle of the spring relative to the gauge so the turns match up with the lines. At the right end, count any additional fractional turn to the cut end.

For additional instructions on how to count spring turns, see:
<http://springipedia.com/compression-counting-coils.asp>

Recoil Spring Turns-Counting Gauges

